





Cold air-jet for hydrophobic IOLs machining :

A cold air-jet  (- 12°C and 7 bars) is blown along or under the tools.



GFT- M - Nai

Removable nose for a quick change of milling-tool

